



Dealer : SC AUTO COBALCESCU SRL
 Sediul: SPLAIUL UNIRII, NR. 311
 SECTOR 3, BUCURESTI, ROMANIA

Telefon
 Nr. Reg. Comert.: J40/12025/1991
 CUI : R01590376
 Banca:
 IBAN

Nr OR/Echipa/Nr intrare : 320110677 / At SPLAI Mec I/
 Nume Consilier Service:
 Telefon:
 Nr. intern: 998241
 Nr. Deviz: Clifac 1

Client Societate SD3 - SALUBRITATE SI DESZAPI
 Sediul: SECTOR 3
 Nr. Ord. Reg. Com./an: J40/9896/2017
 CUI/CNP: R037804020
 Banca:
 IBAN:

Proforma

Pag	Serie sasiu	Data reparatiei	Kilometraj	Nr inmatriculare	Tip APV	Data livrare	
1	VF1FW000464420269	18.12.2023	31557	B987SDZ	=W1	18.12.2023	
Denumire produs sau servicii	Cuseta	Cod	Cant/Timp	Valoare unit (fara TVA)	Red %	Pret Unit net	Valoare total (fara TVA)
Manopera							
1	OG REVIZIE VEHICUL	MC010048	1,30	250,00	10,00 %	225,00	292,50
2	OG INLOC FILTRU HABITACLU	MC016170	0,10	250,00	10,00 %	225,00	22,50
TOTAL(fara TVA)Manopera							315,00
Piese							
3	FILTRU HABITACLU	200122	8201676037.	1,00	110,64	10,00 %	99,58
TOTAL(fara TVA)Piese de schimb							99,58
TOTAL (fara TVA)						414,58	
TVA						78,77	
Numar ore facturate:		1,40 ore		TOTAL factura			493,35